





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, AD, ..

**Position**



- 1 = A 962046 XX
- 2 = A 963667 NU
- 3 = A 962041 NU
- 4 = A 961485 XX
- 5 = A 961667 NU ( 2x )
- 7 = A 963372 NU
- 8 = A 962715 NU
- 9 = A 962716 NU
- 11 = A 962047 XX
- 12 = A 960445 NU
- 13 = A 962048 XX
- 14 = A 960395 NU
- 15 = A 963651 NU
- 16 = A 962594 NU ( 2x )
- 18 = A 961182 NU ( 2x )
- 20 = A 961139 NU ( 2x )
- 22 = A 962049 XX
- 24 = A 962050 XX ( 2x )
- 25 = A 2401 XX
- 26 = T 2439 XX
- 27 = A 3306 XX



**MELANGE**


**A 4269 .. A 4270 .. A 4271 .. A 4272 ..**





0811/ A 865 800  
 (+A 865 612)



Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)





	<b>P</b> bar	0,5	MAX. 10		5		<b>Q</b> (3 bar)
	<b>T</b> °C		MAX. 80		65		<b>I/min</b> 20,5

