





Jacob Delafon

TOOBI







E8993-**




P	Bar
0.5 < 3 < 6	

T	°C
55 < 60 < 65	



1




2




3





4




5




1




2




3




4




5




6















7



8







SERVICE ASSISTANCE CLIENTÈLE : ☎ 03 26 49 57 29
 SAT ESPAÑA Y PORTUGAL : ☎ 902 11 38 36
 ООО КОЛЕР РУС : ☎ +7 495 783 5223

Jacob Delafon